

May 30, 2018 CH1805-06

Connie Simiele, Assistant Manager, Plutonium Finishing From:

Plant Recovery

To: CHPRC Employees (please cascade)

PFP UPDATE: IMPLEMENTATION TODAY - NEW WORK CONTROL Subject:

ZONE AND RADIOLOGICAL BUFFER AREA

At the end of the day today, new Radiological Buffer Area (RBA) and work control zone at the Plutonium Finishing Plant will go into effect. Details of the new boundaries are described in this May 14 all employee message.

A map showing the new RBA and work control zone is here.

Please follow all postings. If you have questions, please call the PFP Shift Office at 373-0891.